

Turfguard Pro Plus Professional Sprayer

Product Description

This unique 25 litre electronic sprayer with removable tank, battery and battery charger is now easier to assemble and maintain. The Turfguard sprayer has been specifically designed so each 25 litre tank will cover 500 sq.m. The new construction means the machine is lighter therefore easier to use and transport and its 3 nozzle boom comes complete with 2 sets of nozzles. It has been specifically designed for professional users such as bowls clubs, cricket squares, golf and sports clubs, as well as estates and large gardens.

Specifications

This latest version of this unique proven pedestrian sprayer now features:

- A new lightweight frame
- New designed ball bearing wheels
- Quick release hose joints
- Improved filtration system
- Clear hose for visibility checks
- Revised electrical charging point
- Simplified on/off system
- Weighted tank feed assembly for more efficient tank uptake



Full range of spares and spare tanks available.

If you require spares, email us a picture of the part/s required so we can replace it accurately.

Also Available... **NEW Turfguard Hand Lance**



Increase the versatility of your Turfguard by attaching a Hand Lance. The Turfguard Pro Plus Hand lance can be fitted to your Turfguard Sprayer with ease, and once connected this will be ideal for spot spraying without the need of a knapsack sprayer.

Available and in stock from Collier Turf Care
Contact your local Area Technical Sales Representative



Turfguard Pro Plus Reduced Pressure

We are becoming increasingly aware that some products used with our spraying machines have resulted in a residue build-up inside the pump-heads. Such build-ups can directly affect the pressure output from our pumps.

We always advise that all sprayers are thoroughly cleaned after every use, paying attention to flushing the pump and spray booms with clean fresh water.

Further, we recommend the regular use of **Prestige Super Tank Cleaner** to ensure that all sprayer equipment is maintained at peak performance.

Lack of pressure? / Not all nozzles are working?

1. Check all the spray nozzles and nozzle filters are clean!

Clean filters and replace any blocked nozzles. – **Do Not** "poke" the nozzle hole in an attempt to clean it! If attempted this will result in damaging the nozzles integrity, and will directly affect the spray pattern/flow rate of the nozzle.

2. If all nozzles and filters are clean and free of blockages, this will indicate a reduction of pressure produced by the spray pump.

- Check that the battery is fully charged and in good condition.
- Check all pipes and connections for signs of leakages.
- Ensure the main filter is secured tightly, always ensure that the filter seal is fitted correctly.
- **DO NOT** open the valve on the side of the offending spray head. This is a low pressure cut off valve and has **NO** effect on the pressure or flow rate produced by the machine's pump. By opening this valve, the overall pressure in the sprayers system is reduced, this will have a negative affect on the machine's spraying efficiency.

3. Cleaning the pump.

- Half fill the spray tank with warm water.
- Switch the pump on and spray through the system until warm water is discharged through the nozzles, spray for 1 -2 minutes.
- Switch the pump off and allow warm water to dissolve any residue build-up.
- Switch pump on again after 2 minutes, this should improve the performance of the pump, if not repeat the process.
- If there is no significant improvement after repeating this process contact your Collier Turf Care advisor.

